

Slope Chart in Degrees

0.5 degree = 0.87 percent
1.0 degree = 1.75 percent
1.5 degrees = 2.62 percent
2.0 degrees = 3.5 percent
2.5 degrees = 4.37 percent
3.0 degrees = 5.24 percent
3.5 degrees = 6.12 percent
4.0 degrees = 7 percent

Slope Chart in Percent

.5 percent = .29 degrees
1 percent = .57 degrees
1.5 percent = .86 degrees
2 percent = 1.15 degrees
2.5 percent = 1.43 degrees
3 percent = 1.72 degrees
3.5 percent = 2 degrees
4 percent = 2.29 degrees
4.5 percent = 2.58 degrees
5 percent = 2.86 degrees
5.5 percent = 3.15 degrees
6 percent = 3.43 degrees
6.5 percent = 3.72 degrees
7 percent = 4 degrees